4946

F. C. Causes of Fire

6 - San Diego

Location where welding operations started Staite Fire. Clearing to mineral soil not adequate.

8-7-53 - Norm Harris